

LUMPKIN COUNTY SURVEY  
BY  
ELIZABETH LYON AND JENNY THURSTON

- 1) Introductory Statement
- 2) Survey Forms  
1-47 (Dahlonega)  
48-109
- 3) Photographic Survey  
158 slides
- 4) Map (1 in front pocket)

HISTORIC STRUCTURES FIELD SURVEY EVALUATION: Lumpkin COUNTY

GENERAL SURVEY ASSESSMENT:

This survey attempts to document all properties within Lumpkin County that meet the criteria for National Register listing.

COMPONENT ASSESSMENT:

DESCRIPTIONS:

Slides are sharply focused, well framed, and correctly exposed. Each property is fully described by style, date, facade material, plan, etc. Notes supplement the descriptions and slides.

STATEMENTS OF SIGNIFICANCE:

Some statements of architectural and historical significance are given. Comments often supply information on historical significance.

MAPS:

The Lumpkin County map is in fair condition. Although each location is clearly marked, some are smeared or faded since they are marked in ink.

OTHER:

SURVEYOR'S QUALIFICATIONS:

Jenny Thuston was at one time a preservation planner for the Historical Preservation Section. She is now the Executive Director of the Macon Heritage Foundation.

DATE OF SURVEY:

February 1976

SURVEY COVERAGE: (geography, chronology, type/style, individual-district sites)

This survey covers the accessible roads in the county. Private roads and those not easily travelled were not surveyed.

Both individual and district properties have been located.

\*USE OF THIS SURVEY SHOULD BE CONDITIONED BY THE FOLLOWING CONSIDERATIONS:

This survey may be used with confidence. The information is reliable and the surveyor successfully met the goals of the survey. This is a comprehensive survey of the architectural and historical resources of Lumpkin County.

REVIEWER

Patricia D. Wilson

DATE OF REVIEW

February 30, 1980

NOTE: A MORE DETAILED REVIEW AND EVALUATION OF THIS SURVEY IS ON FILE AT THE HISTORIC PRESERVATION SECTION OF THE GEORGIA DEPARTMENT OF NATURAL RESOURCES.

**\*OVERALL SURVEY ASSESSMENT:** This survey attempts to document all properties within --1976 Lumpkin County that meet the criteria for National Register listing.

**COMPONENT ASSESSMENT:**

**SURVEY COVERAGE:** This survey covers the accessible roads in the county. Private roads and those not easily traveled were not surveyed. Properties of various types/styles have been included. Most structures are simple and vernacular. Both individual and district properties have been included.

**DESCRIPTIONS:** Slides are sharply focused, well framed and correctly exposed. Each property is fully described by architectural style, construction date, facade material, and floor plan. Notes supplement the descriptions and slides.

**STATEMENTS OF SIGNIFICANCE:** Some statements of architectural and historical significance are given. Comments often supply information on historical significance.

**MAPS:** The Lumpkin County map is in fair condition and is easily cross-referenced to the survey forms and the locality map. Although each location is clearly marked, some are smeared or faded since they are marked in ink. The properties marked on the Dahlonega map are barely legible.

**SUMMARY OF COUNTY DEVELOPMENT:** There is a good summary of Lumpkin's county development which addresses the historical development and the architectural characteristics of the county.

**SURVEYOR'S QUALIFICATIONS:** Jenny Thurston was at one time a preservation planner for the Historic Preservation Section. She is now the Executive Director of the Macon Heritage Foundation. Jenny also surveyed Dawson, Forsyth and Hall counties in the Georgia Mountains APDC.

**DATE OF SURVEY:** February 1976

**OTHER:** Two districts and several individual structures were recommended as possible National Register nominations.



**\*USE OF THIS SURVEY SHOULD BE CONDITIONED BY THE FOLLOWING CONSIDERATIONS:**

This survey may be used with confidence. The information is reliable and the surveyor successfully meets the goals of the survey. This is a comprehensive survey of the architectural and historical resources of Lumpkin County, however, history is not emphasized as much as architecture.

**PREPARED BY:** Patricia D. Wilson      **DATE OF REVIEW:** February 18, 1980

**NOTE:** A MORE DETAILED REVIEW AND EVALUATION OF THIS SURVEY IS ON FILE AT THE HISTORIC PRESERVATION SECTION OF THE GEORGIA DEPARTMENT OF NATURAL RESOURCES.

Nos. 1-47  
--1976



DAHLONEGA  
LUMPKIN CO.  
GEORGIA

**EXISTING  
LAND  
USE**


GEORGIA MOUNTAINS PLANNING  
AND DEVELOPMENT COMMISSION

PREPARED BY  
1976

APPROVED BY  
*R. Anglin*  
DATE  
APRIL 1988

NOTES:  
1. THIS MAP IS A GENERALIZATION OF THE DATA PROVIDED BY THE DAHLONEGA PLANNING AND DEVELOPMENT COMMISSION. THE COMMISSION IS NOT RESPONSIBLE FOR ANY ERRORS OR OMISSIONS.  
2. THE COMMISSION IS NOT RESPONSIBLE FOR ANY ERRORS OR OMISSIONS.

1-11-77



**LEGEND**

- RESIDENTIAL
- COMMERCIAL
- PARK & SEMI-PARK
- VACANT & AGRICULTURAL

DAHLONEGA  
LUMPKIN CO.  
GEORGIA

**EXISTING  
LAND  
USE**

GEORGIA MOUNTAINS PLANNING  
AND DEVELOPMENT COMMISSION

Prepared by  
1-1-77

Approved by  
*K. D. ...*

DATE  
April 1977

EXISTING  
LAND  
USE

DAHLONEGA  
LUMPKIN CO.  
GEORGIA

GEORGIA MOUNTAINS PLANNING  
AND DEVELOPMENT COMMISSION  
GADSDENVILLE, GEORGIA


PREPARED BY  
1976

APPROVED BY  
*R. M. [Signature]*  
DATE  
APRIL 1976

SCALE  
1" = 1/2 MILE

LEGEND

- RESIDENTIAL
- COMMERCIAL
- INDUSTRIAL
- UNCLASIFIED PUBLIC
- VACANT & AGRICULTURAL



Report

Lumpkin County

Prepared by Elizabeth A. Lyon,  
Consultant, and Jenny  
Thurston, Surveyor

February, 1976



A History of Lumpkin County by Andrew W. Cain, which covers the first hundred years from 1832-1932, provided the surveyor with general historical information. The discovery of gold in 1828 by Benjamin Parks on property now known as the Calhoun Mines is the most important factor in the history of the area, although few actual structures remain from these early days. The removal of the Cherokees, via the "Trail of Tears," and the parceling of their land into 40 acre gold lots and 160 acre farm lots is generally known information which was important to the physical development of the area. At the time that the county was created in 1832, following the discovery of gold, the town of Auraria was developed in response to the large influx of people. The community was first called Nuckellsville after Nathaniel Nuckells, who built a hotel there in 1832, but since 1833 has been known as Auraria. It is reported that the town in its early years numbered several thousands but that after the decline in gold mining in the 1850's in the area it began losing population. Of the 18-20 stores, 4-5 taverns and 15 law offices reported to have originally been in the town, only a few structures, some of later nineteenth century date, remain. The county's oldest church, Antioch Baptist Church, is now in a rebuilt structure although its cemetery dates back to gold mining days.

Dahlonega became the county seat in 1833, and the present courthouse replaced the original log structure in 1836. A branch of the U. S. Mint was opened nearby in 1838.



-2-

Subsequently, the old mint, closed at the outbreak of the Civil War, was destroyed. On its foundations Price Memorial Building of North Georgia College was built in 1879. Buildings on the east side of the square have replaced an old hotel built by an early settler, Harrison Riley, but those on the west side constructed by a gold miner, Frank Hall, in the 1870's remain.

In addition to Cain's history of the county, articles on the development of the gold industry written by Dr. Fletcher Green detail the early history of this area. According to one informant, Frances Jones is now writing a new history of Lumpkin County. Several local contacts provided sites information to the surveyor: Mrs. Ida Philips, Vice President, Dahlonega-Lumpkin County Historical Society; Mrs. Madelaine Anthony, ex-curator of the Gold Museum that is now housed in the courthouse, who has collected much information on the county; Dr. Ray Rensi, of the Social Science Department of North Georgia College who has collected data about old families and county history; J. Marlin Smith, Superintendent of Schools; Lee Duval, Laurel Knob Gift Shop in Auraria, who came to the county about eight years ago from Florida and has collected old photographs and mining history information; Ralph Yates and Reese Scull, U. S. Forest Service, Chestatee Ranger District in Dahlonega.

Not as many original families in old homeplaces were found in this county as in Forsyth and Dawson Counties. The surveyor did not find as many early, plain-style and simple cabin type

-3-

of structures here. Traces of older structures, dilapidated houses and outbuildings, including log barns, were found. She also observed an unusual number of log structures, outbuildings as well as dwellings. It appears that either log buildings continued to be constructed late in the 19th century here, or that a number of the outbuildings belonged to houses that have since been replaced by newer buildings. There was evidence of more extensive recent building, including many brick homes, in this county that in the others also.

The United States Forest Service bought up approximately 57,000 acres in Lumpkin County beginning in the late 1930's. Ms. Thurston conferred with forest rangers Ralph Yates and Reese Scull of the Chestatee Ranger District headquartered in Dahlonega, who reported that few extant structures remain in the forest. They provided names and locations for some of the buildings in the forest area, but access by automobile to much of the area was not possible.

At least two districts in this county would make eligible National Register Districts. In addition to the County Courthouse, which is already on the Register, several buildings around the square form a district area (Nos. 1-8). Hall's Block (No. 5) is a particularly nice example of a mid-century Italianate business block which is associated with the gold mining history of the county. Auraria, because of its representation of early gold mining history and extant early structures, is a second district (Nos. 51-56). This area, suggested as a pos-

-4-

sible heritage site in 1973, contains a hotel, c. 1833, a general store that is still in use, three houses (two early abandoned buildings and one of 1890), a c. 1910-20 bungalow occupied by the present owner of the store, and an old graveyard behind the rebuilt Antioch Baptist Church which contains graves of old Auraria gold miners and some Civil War markers in a finely detailed iron enclosure. There are several interesting church buildings which should be considered of potential architectural significance. St. Lukes Catholic Church (No. 14) is a nice example of a small frame, modified Victorian building with wooden tile patterns in multiple gables. Wesley Chapel Baptist Church (No. 109) is a frame building entered through an octagonal-shaped weather boarded-tower and has a cemetery with several nice Victorian monuments. Nimblewell Baptist Church (No. 106) is a small white frame structure with weather-boarding in a fan pattern in its triangular gable. Two structures associated with the gold mining history of the county are the Welch Home (No. 23) believed to date from c. 1836 and to be the oldest extant house in the county, and the Fry Home (No. 37), a Victorian, Queen Anne structure built by Colonel Fry who was the head of the Calhoun mines. The Smith House (No. 30), while not particularly outstanding as an architectural monument, nonetheless is typical of its turn-of-the-century date and has an interesting history as a well-known Dahlonega hotel. The Davis homeplace (No. 59), built c. 120 years ago, is a good example of a plain-style structure elaborated with Greek Revival

-5-

type detailing with extant outbuildings. The Old London Farm, with extant London store building that once served a stage route (No. 66); the Tate Farm (No. 91), with nicely detailed plantation plain-style house and outbuildings, one partially of log construction; and the Barnes Farm, with remains of a water wheel, are three ensembles of local significance. One outbuilding (No. 93) is also of architectural interest. It has an unusually complex plan and detailing of flush diagonal boarding on the facade. The large number of log structures merit further evaluation (Nos. 68, 69, 70, 85, 92, 96, 102, 103, 100 and 198). In addition, the Poore House (No. 64) is a house built to connect an extant log cabin, c. 1815, to a log kitchen which is reported to have connections to Indian history.

114, 0-2

Number 1

County Lumpkin

Name of structure Old Lumpkin County Courthouse - Gold Museum

Location Town square in Dahlonega

Present owner Department of Natural Resources

Original owner Lumpkin Co. Architect/builder \_\_\_\_\_

DESCRIPTION

Style Greek Revival

Facade Material Brick

Outbuildings \_\_\_\_\_

Plan Symmetrical

Alterations Front projection added

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 2 story Red Brick building with Greek Revival proportions. Front has four Tuscan columns, inset gables, Fan lights around double doors. 2 side brick chimneys. 12 1/2 light windows. Round louvers in side gables

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

District - state

Additional Comments:

From Georgia Historical Marker: Built in 1836, replaced the small log structure used since establishment of county in 1832. Town named Dahlonega in Oct, 1833 for Cherokee word, "Talonaga", meaning golden. Gold was discovered in Georgia by Benjamin Parks in 1828. See National Register form.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January, 1976

Don Stewart

Name of structure Robert M. Moore Office and Apartment Building

Location Dahlonega Town Square

Present owner Robert Moore

Original owner Frank Hall Architect/builder \_\_\_\_\_

DESCRIPTION

Style Victorian - Eastlake details

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Two story frame building which originally was used as a boarding house. 2nd story porch has square posts, brackets and spool work balustrade. Four dormer windows above second story. Round iron columns in front. Elliptical shaped windows in single front door. Mansard-type 3rd story

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

District state

Additional Comments:

This building was built by Frank Hall, c. 100 years ago. Hall was a gold miner and owned the store next door. He built this building with his hands who helped him at the mines and it was referred to as Hall's Boarding house.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Don Thurston

Name of structure Jones House

Location Dahlonega Town Square

Present owner \_\_\_\_\_

Original owner C.H. Jones Architect/builder \_\_\_\_\_

DESCRIPTION

Style Modified Queen Anne

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Recently restored/remodeled

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 2 story frame house built c. 1870's according to Ida Phillips. Porch  
 extends along 3 sides. Rectangular porch posts. Multiple gables with boxed cornice  
 and returns. 6/6 light windows. Carved detail on front door. Stained glass in door panes.  
 Spool work under porch eaves. Interior brick chimney

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

District - state

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January



Name of structure Olson's Craft Gallery and Dahlonega Coin Shop

Location Dahlonega Town Square

Present owner Burt Lavine (in Lawrenceville)

Original owner Dr. Head Architect/builder \_\_\_\_\_

DESCRIPTION

Style Early Victorian

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

2 1/2 story frame building with 2nd story porch with chamfered brackets and single rail balustrade. Dormer windows above 2nd story. Detail cornice board. Transom and sidelights. Broad gable above 2nd story, also.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

District - state

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Dr. E. H. ...

Number 5 County Lumpkin

Name of structure Foodland store (Kenner) - Hall's Block

Location Dahlonega Town Square

Present owner \_\_\_\_\_

Original owner Frank Hall Architect/builder \_\_\_\_\_

DESCRIPTION

Style Italianate

Facade Material Brick

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Two story commercial brick building with 6/6 light windows. Paired  
 brackets under cornice. Incused detail in bricked on facade. Small light windows above  
 door. Frame windows with carved detail. Bars on windows original (when gold  
 mines used to bring gold here in exchange for cash). Bricks for this building were made  
 at factory near where city cemetery is now (near Gallus Hollow)

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

District - state

Additional Comments:

This building was built by Frank Hall, a gold miner. He  
 operated a general store on the main level; downstairs was for mining  
 supplies; upstairs, he kept the gold which miners sold to him. C. 100  
 years old

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Chris Thurston

Name of structure N. A. Nix Grocery

Location Dahlonega Town Square

Present owner N.A. Nix

Original owner Architect/builder

DESCRIPTION

Style Plain - style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 story frame store with clustered posts. Single rail balustrade  
2nd story porch. Recessed front gable. 9/6 light windows upstairs.  
Double door with light windows.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

District - state

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 Jan

Surveyor Don Shumaker

1000

Number

7

County

Lempkin

Name of structure Apple Anns, Bobbie's Salon

Location Deklonge Town Square

Present owner Mrs. John H. Moore

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Commercial

Facade Material Brick

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Two story brick structure with stepped back work under eaves. I like type balustrade in interior of building. Raised flower detail in interior ceiling.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

District - State

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 Jan

John H. Moore

Number 8 County Lumpkin

Name of structure Old Meadows house (now Gold City Restaurant + Sisk Auto House)

Location Main Street Dahlonega

Present owner Jake Palmer

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame ; stone facade now brick

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: Originally was a frame structure. brick facade has been built and frame. Old residence is now used for apartments. Bannister and <sup>balustrade</sup> ~~steps~~ of frame building - cast like in detail. weatherboarding doesn't overlap <sup>(not-ground)</sup> 4/4 light windows

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

District - state

Additional Comments:

Old Meadows house <sup>stone</sup> built c. <sup>late</sup> 1830's (according to Mrs. Anthony); one of oldest structures in county. Inner part is frame; <sup>now</sup> with brick facade.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 Jan 1976

Surveyor John Shuster

Name of structure Old Christian home

Location 210 Warwick Street, Dahlenega

Present owner Mrs. Garner

Original owner Christians (later) Architect/builder \_\_\_\_\_

DESCRIPTION E.W. Strickland

Style Pl. Plain - style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Symmetrical; central hall

Alterations Recently remodeled; New iron work on porch

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 2 story red frame house, with 9/9 light windows. Small gable over front door. 2 internal brick chimneys. Boxed gables and cornice board with returns.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 Jan

James Thurston

Number 10

County Lumpkin

Name of structure \_\_\_\_\_

Location Wocurck Street, Dahlonega

Present owner \_\_\_\_\_

Original owner Dan Early Architect/builder \_\_\_\_\_

DESCRIPTION

Style Pl. Plain-style, Early Victorian porch

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations later addition in rear

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

Two story frame with 6/6 light windows. Turned porch posts and brackets. In some windows over 2 front doors. 9/6 " " upstairs. Side interior brick chimney. Dipped cornice and returns. Also outside brick chimney

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one here

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 Jan

Dan Early



Name of structure \_\_\_\_\_

Location N. Chestnut Street, Dahlonega

Present owner Nelle Brown

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Pl. Plain-style -

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Central hall

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: Two story frame with 9/9 light windows downstairs and 9/6 upstairs. Front porch has square porch posts and cast-iron balustrade. Small rectangular railing over cornice. Small second story porch projects from gable; turned posts. Light window (transom) above door. Shed porch at rear. T-type projection in rear. Outside brick chimney. Front gable projects over 2nd story porch.

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:  
No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

200-26

Number 12

County Kingston

Name of structure \_\_\_\_\_

Location 308 Waters Street Dahlanee

Present owner Mrs. Deafhillips

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Pl. Plain - style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Additions in rear

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

Two story frame with exterior stone/brick chimney. 9/6 light window  
 part of both 1st + 2nd story. 1st story porch has replaced metal-like railing; 2nd  
 story - turned posts and single rail balustrade. Boxed cornice with flat returns.  
 Tin roof

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Deafhillips

R.M. 57

Number 13

County Lumpkin

Name of structure \_\_\_\_\_

Location 580 N. Chestnut Street, Dahlonega

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan T-plan

Alterations Covered with shingles; additions on west side

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: Two story frame with T-projection in rear. 4/4 light windows. One exterior chimney. Small gable over porch; porch has paneled posts. Boxed cornice & returns. Carved detail in front door. Shed porch screened in on east side.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments: No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

De... Turner

Name of structure St. Luke Catholic Church

Location Dahlonega

Present owner St. Luke Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Victorian (Queen Anne?)

Facade Material Fraume

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Tall 2 story frame church with steep and broad front gable with 4/4 windows. Small gable projections over front doors. Rectangular steeple on west side with wooden louvers and 6/6 light windows. Detail under eaves of steeple.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Name of structure \_\_\_\_\_

Location 270-280 Meaders Street, Dahlonega

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Late Victorian

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

1 1/2 story frame with 3 dormers with stained glass windows and a front porch on right side with louvers. Porch extends across front and around side with chamfered posts and brackets. single railing balustrade. Two brick interior chimneys. 4/4 light windows. Cornice board under eaves. Tin roof

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home. <sup>Perhaps is a</sup> Two family house now.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Surveyor Jim Thurston

Name of structure Mason's Produce

Location Corner of Meaders and Hawkins Street, Dahlgren

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style ~~1st Victorian~~ Early Victorian - Plain style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 story frame store which appears to have been built at same time  
as next door. 2 porches with chamfered posts and brackets. Front A-line gable  
Porch extends across front and side and has lattice balustrade

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Surveyor [Signature]

Name of structure Higgins residence

Location 110 Grove Street, Dahlonega

Present owner Higgins

Original owner Rogers? Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Central hall

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

2 story frame with 6 square columns. 6/6 light windows. scallop shape above door. Small balustrade on roof. Two front dormers and 2 brick interior chimneys. Boxed gables and returns. Additions in rear.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 Jan

*Dr. 11. 7*



R14,34

Number

18

County

Hampton

Name of structure Pruitt home place

Location Grove Street, Dahlanega

Present owner Mr. Butler

Original owner Pruitts Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Two story frame with two exterior brick chimneys. Small front gable double louvers. Small gable over front porch. 6/6 light windows. T-projection rear. Two square porch posts.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 Jan

Thurston

Name of structure Vicker-Sisk Funeral Home

Location 400 Grove Street, Dahlenega

Present owner Vicker-Sisk

Original owner Frank Thompson Architect/builder

DESCRIPTION

Style Late Victorian

Facade Material Frame

Outbuildings

Plan Central hall

Alterations

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

2 1/2 story frame with front porch with tapered square type posts and like belustrede. Double front door with transom and sidelights (stained glass) right hand door on front has side and fan lights. Small porch on 2nd story, hipped roof above house. Side dormers. Two central internal brick chimneys. Lovely site; spacious grounds.

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Mrs. Potter, a former resident of the house, believes the house was built in 1898 by a mason named Frank Thompson. She said it originally had a leaf molding.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Frank Thompson

Name of structure Victory House  
Location Main Street, Dahlonega  
Present owner Dahlonega Club  
Original owner Victory's Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_  
Facade Material Frame  
Outbuildings \_\_\_\_\_  
Plan Asymmetrical  
Alterations Being restored, new shingled roof.  
Condition  
Structure 

Good	Fair	Poor	Endangered
<u>✓</u>	_____	_____	_____
Grounds	_____	_____	_____
Neighborhood	_____	_____	_____

Notes: 2 story Victorian frame with porch extending across front and side. <sup>or carriage porch</sup> Shed porch at rear. Side gable over 2nd story with square louver.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: Mrs. Ida Phillips believes that the original part of this house is log.

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Built c. 1890<sup>60</sup>'s according to Ida Phillips, but has original rooms of 1890's. Mr. Victory taught at North Georgia College. Miss Victory gave house to Dahlonega Club this past summer.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January  
Thermon

R 14, D

Number

21

County

Lumpkin

Name of structure Price Memorial Hall

Location North Georgia College, Dahlonega

Present owner North Georgia College

Original owner " " " " Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Brick

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Leaving of steeple with gold from surrounding hills in 1873.

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 1/2 red brick building with 4 Tuscan front columns, <sup>4 pilasters</sup> 6/11 light windows. Dormer lights above <sup>3 dormer</sup> doors at front. Brackets under eaves. Side gables with louvers. Elliptical arches over rear windows. Steeple projects from mansard type roof. Side porch with turned posts.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

See National Register form. According to the Georgia Historical Commission marker, in 1837 the U.S. branch mint operated until seized by the Confederates in 1861. In 1871 mint by and 10 acres of land transferred to state for agriculture college. With help of Rep Willie Jones - founder of North Georgia College. Mint building destroyed by fire in 1878. In 1879 second building constructed on foundations.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

*Dr. H. T.*

Number 22

County Hampton

Name of structure Mt. Hope Cemetery

Location Dahlgren

Present owner "

Original owner Architect/builder

DESCRIPTION

Style \_\_\_\_\_

Facade Material \_\_\_\_\_

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Many old graves. Several dating back to 1830's and 1840's. Parker dates to 1840 (William Allen) who was a Private 45C Regt. in Revolutionary War. Several interesting Victorian monuments. Good example of iron railing.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Mrs. Jeda Phillips told me that there was a coloured section in the cemetery, but now Blacks and Whites are buried together

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Number 23

County Lehigh

P 14, 15  
R 17, 33

Name of structure \_\_\_\_\_

Location Hwy. 60 in Dahlenaga

Present owner Fred Welch

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plain - style - Georgian

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Symmetrical, central hall

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 2 story frame with 9/16 light windows. Side gables. Side shed porch. Gable projects over front door. Internal brick chimneys.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: Mrs. Ida Phillips and Mrs. Magdaline Anthony believe it to be the oldest extant house in county - c. 1836. A gold mining company is thought to have built it.

Recommendations for National Register (single structure, district, priority):

Structure - State

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Don Stewart

Number 24

County Lumpkin

Name of structure R15, #2  
McAfee home

Location 298 Choice Ave, Dalton, Ga

Present owner Mrs. W.S. Davis

Original owner McAfee Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 2 1/2 story frame with 6 square columns (wider at bottom) resting on brick base. Transom and sidelights around door. 6/6 light windows. Pilaster along facade. 2 story porch with attached balustrade and chamfered posts. 2 central interior brick chimneys. Sidelights around upstairs door. Boxed cornice and returns.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Talked to housekeeper.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

W.S. Davis



R15, B-4

Number 25

County Lumpkin

Name of structure \_\_\_\_\_

Location N.E. Corner of Choice + S. Park, Dahlonega

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Late Victorian

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 2 1/2 story frame with front gable ~~with~~ which has flush boarding. Hipped roof over main body of house. 1st story porch with paired square porch posts and spool like balustrade. 2nd story porch has chamfered posts + single rail balustrade. 4/4 light windows. Integral brick chimney. Bay window on rear right side. Raised detail on door.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

*Dee Stewart*

RIS, 5-7

Number

26

County

Lumpkin

Name of structure \_\_\_\_\_

Location NW Corner of S. Park + Maple - 37 S. Park; Dahlonega

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_

Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Additions in rear

Condition

Good

Fair

Poor

Endangered

Structure ✓

Grounds ✓

Neighborhood ✓

Notes:

2 story frame with 8 paired square columns in front. 2<sup>nd</sup> story porch w/ spool-like balustrade. Scalloped and diamond shaped tiles in front gable. 2 brick chimneys. Flushed boarding on facade. Transom window. Patterned glass in front door. Pilasters along facade.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Possibly Victorian entrance portico in mid-19<sup>th</sup> century "Greek Revival - Placidian Style Home" ? EdL.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Don't think it's

158

Number 27

County Lumpkin --1976

Name of structure \_\_\_\_\_

Location 308 S. Park ; NW Corner of S. Park + Martin, Dahlonega

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Late Victorian - Queen Anne, Eastlake porch

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Asymmetrical

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 story frame with front porch which extends along side. Turned posts for posts and Eastlake balustrade. Spool work under porch eaves. Flushed boarding facade. Transom window above carved door. Front bay window. Scalloped and diamond tiles in front and side gable. 2 interior brick chimneys

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Don Thurston

R15, 9-10

Number 28

County Lumpkin

Name of structure Phillips residence

Location SE corner of S. Park & Martin, Dahlonega

Present owner Phillips

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Late Victorian

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 2 story frame with full length windows on front. Transom and side lights around door. Front porch has chamfered posts and flat scroll work. Front bay window. 6/6 light windows. Front gable with cornice board and louvers. Side porch with flat scroll work brackets and chamfered posts. Interior brick chimney. Cornice board and returns.

Architectural (Local, State, National) Discuss: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):  
 \_\_\_\_\_

Additional Comments:  
No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Don Thurston

215, 11 2

29

Number

Lumpkin  
County

Name of structure Seven Oaks

Location 460 S. Park, Dahlonega

Present owner ~~Colonel William P. Price~~ North Georgia College

Original owner Colonel William P. Price Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Front porch screened in, winding awnings

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 1/2 story frame with 2 front dormers. Interior brick chimneys. Light windows. Transoms and side lights. Chamfered posts on back porch. Tin roof. Gable with boxed cornice and returns. Dormer windows

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Colonel Price was the founder of North Georgia College. The house was built in 1871. The house has been donated to the college by a granddaughter of Colonel Price. He, at one time, owned several of the houses along S. Park, which he bought for members of his family.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Surveyor Jenny Thurston

R15, 13

Number 30

County Lumpkin

Name of structure \_\_\_\_\_

Location 461 S. Park

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Pl. Plain-style - Greek detailing

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Central hall

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 story frame with 4 Tuscan columns. Transom and side  
lights. 6/6 light windows. 2 exterior brick chimneys. Possible later  
acquisitions in rear. Cornice board

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January  
Surveyor John Thurston

R151

Number 31

County Lumpkin --1976

Name of structure \_\_\_\_\_

Location 408 S. Park, Dahlonega (Sw corner of S. Park & Arcadia)

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Screened porch on side

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 story frame with transom and side lights. 4/4 light windows  
Dormer windows  
In posts in front support small gable. Interior brick chimneys

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Surveyor James Thurston

R15, 15

32  
Number

Lumpkin  
County

Name of structure Gallant residence

Location 566 S. Park - NW Corner of S. Park and Arcadia, DeKalb County

Present owner Gallant

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

Small 2 story frame with small porch with turned posts, brackets and brackets. Front bay window. 2/2 windows. Front gable has scalloped and diamond shaped tiles. Tiles within full length of gable. Stained glass in front door which was covered detail.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Surveyor James D. Thurston



RIS, 16-17

Name of structure \_\_\_\_\_

Location 612 S. Park Dahlonega - NE corner of S. Park + Arcadia

Present owner W. A. Hedden

Original owner Col. Price Architect/builder \_\_\_\_\_

DESCRIPTION

Style Mid Victorian (Mr. Hedden referred to it as "General Grant Gothic"!

Facade Material Frame (Not right, more  
Grec Revival in feel - EdH)

Outbuildings Well house

Plan Central hall

Alterations New porch

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 2 story frame on very spacious grounds. Original facade had shed porch 7ft high for removed 2nd story porch and put up <sup>square</sup> columns in 1940's. 6/6 light windows. Side gables and transom. Front gable with <sup>(recessed)</sup> scalloped shaped tiles (added later as was front bay window. Interior brick chimney.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Built in 1888 by Colonel Price for his son-in-law (Wilson)

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Surveyor Jenna Thurston

Number 34 County Henry/Kear

Name of structure Jackson home

Location S. Park, DeKalb

Present owner Flossie Jackson

Original owner T.F. Jackson (father of present owner) Architect/builder

DESCRIPTION

Style Late Victorian

Facade Material Frame

Outbuildings

Plan Central hall

Alterations New metal roof

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: built c. 1900. Two story with front gable. Porch has rec-  
ular posts and balustrade. 4/4 light windows. Gable with boxed  
cornice and returns. A-shaped louvers. Front gable projects over small second  
story porch with balustrade.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

D. H. T.

Name of structure Ash homeplace

Location 506 S. Park Dahlonega

Present owner Louise Riddle

Original owner Mr. Ash (Mrs. Riddle's Architect/builder

grandfather

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Central hall

Alterations Porch added.

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 story frame with 4 square porch posts. Second story porch has  
4/4 light windows. Side interior brick chimney  
able with boxed cornice and returns.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: Built in 1895 by Mrs.

Riddle's grandfather.

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

Jan. 7, 1976

R15, 20

Number 36

County Lumpkin

Name of structure Gerrard home

Location S Park - NW corner of Park + Tolbert, DeKalb

Present owner Price Bowen

Original owner Marion Gerrard Architect/builder

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Central hall

Alterations Part of rear added; New porch (made it 2 stories instead of 2 separate porches)

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: Two story frame with front gable with cornice board. Two square porch posts and single balustrade. 6/6 light windows. C. 1870 years according to Mrs. Bowen. Interior brick chimney.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

James H. ...

Name of structure Fry home

Location S. Park

Present owner Mrs. Marian Edge

Original owner Col. Fry (Mrs. Edge's grandfather) Architect/builder

DESCRIPTION

Style Queen Anne

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Recently remodeled

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

House c. 100 years old. Two story frame with porch which extends 3 sides of house; chamfered posts; brackets. Front gable with tiles shaped like (zigzag) - zigzagged. Bay window on 2nd story on right side. Multiple gables; Hipped roof over central part of house. Windows 2/2 or 3. Central interior chimney.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Structure - state

Additional Comments:

According to Mrs. <sup>Pine</sup> Bowen, Col. Fry's wife was a pastor at the church across street from house. But since she left that position, they designed the house so that 5 rooms were divided by partitions to enable one large room to be made for home fellowship. Traveling preachers would stay in the bedrooms upstairs. According to Mr. Anthony (head of the Calhoun mine), Mrs. Edge's grandfather came from Ireland and was

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 7 January

*Over the winter*

R 15, 33

Number 38

Sumpter County

Name of structure \_\_\_\_\_

Location 519 Main Street, Dahlonega

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Central hall

Alterations Covered with green shingles, new shutters

Condition	Good	Fair	Poor	Endangered
Structure	✓	_____	_____	_____
Grounds	✓	_____	_____	_____
Neighborhood	✓	_____	_____	_____

Notes:

2 story house with 3 brick outside chimneys. 6/6 light windows. square columns. Single rail balustrade on upstairs porch. Dormer windows

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

Re. with rest

R 15,34

39  
Number

Lempkin  
County

Name of structure \_\_\_\_\_

( ) Location 207 Church Street, Dahlonega

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Remodeled

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

2 story house with 6/6 light windows. <sup>Front</sup> Porch with square posts and  
bracket. Projecting front gable over 2nd story porch. Recessed side gables.  
Outside stone chimney. Rear dormer

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

Jenny Thurmond

Name of structure Smith House

Location Hwy. 60 - Dahlmezer

Present owner Fred Welch

Original owner Captain Frank Hall Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

Hotel part - 2 story with front gable with louver. Porch extends across house with flat scroll work belustrade  
Office - 2 story with gable projecting from hipped roof. Four square posts; 6/6 light windows.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

c. 1900. It was built by Capt. Frank Hall, on top of gold vein; in 1930's purchased by Ben Smith, sold in 1942 to well Smith; in 1946 to W. B. Fry; in 1971 to Fred Welch; since 1930's has been operated as a hotel

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January 1976

Surveyor Jerry Thurston



R16, 34

41  
Number

Lumpkin  
County

Name of structure \_\_\_\_\_

Location Meadow Street, on corner of Maple

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Pl-Plain Style - Victorian porch

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Central hall

Alterations Recent metal roof; Additions in rear

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Two story Planted plain with Victorian porch. turned posts and  
like belustrade. 6/6 light windows. Two exterior brick chimneys. Additions  
in rear. Sidelights around door.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

215, 5

Number 42

County Lumpkin

Name of structure \_\_\_\_\_

Location 310 Martin, DeKaloga (NE corner of Grove St.)

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Addition in rear.

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 2 story with 9/6 light windows. Perhaps front gable and 4 square front columns added later. 2 front doors. Central interior chimney. Brackets under eaves. Lead work above doors and front windows

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

John Thurston

R 16, 7

Number 43

County Lehigh

Name of structure \_\_\_\_\_

Location 311 S. Grove St., Delaware

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Asymmetrical

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 1 1/2 story frame with front gable and hipped roof. <sup>light</sup> 4/4 windows. Central chimney. Porch with turned posts and balustrade.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

R16, 8

44  
Number

Lumpkin  
County

Name of structure \_\_\_\_\_

Location 351 Alma St, DeKalb

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_

Architect/builder \_\_\_\_\_

DESCRIPTION

Style

Late Victorian

Facade Material

Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations

Siding

Condition

Good

Fair

Poor

Endangered

Structure

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Grounds

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Neighborhood


\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Notes:

2 story plantation plain with ~~late~~ Victorian porch. Stone/brick outside  
of porch. Porch has turned posts and balustrade. Tin roof. 7 projection in rear  
Windows —  , stick style ~~frank~~

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

Shirley Thurston

2169

Number 45

County Langston

Name of structure Georgia Forestry Commission office

Location 109 Crota St, Dahlonega

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Italianate

Facade Material Brick

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 2 story <sup>brick</sup> building with 6/6 light windows - bars on 2<sup>nd</sup> floor windows. Steeple with louvers. Vertical brick work above windows. Segmental arched windows.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Perhaps used as Jail at one time

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

Geo. Stewart

217,32 Number 46

Sumner County

Name of structure Dahlonega Baptist Church

Location Highway 60, Dahlonega

Present owner Dahlonega Baptist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Brick


Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Back church with front gable with frame belfry which has  
Crag tiles and rectangular louvers. Two round stained glass windows.  
Front -stepped louver. A type of elliptical stepped windows

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Organized in 1838; present church built in 1897.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Number 47

County Lehigh

Name of structure Park's Store R17, 34-36

Location Main Street, Deltona

Present owner Woodrow & Mrs. H. F. Parks

Original owner M'Guire or Hughes? Architect/builder \_\_\_\_\_

DESCRIPTION

Style Pl-Plain style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New front windows in stone

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

2 story frame building with 9/6 light windows. Front balcony in balustrade. Rear 2nd story porch with balustrade. Corner boards, low set tin roof. Side shed porch.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

According to Mr. Parks, it was built c. 1860's.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Dean Thurston

R16y 9, 20

Number 48 County Lumpkin

Name of structure London home

Location Hwy. 9 E (south)

Present owner J.W. Nix

Original owner Londons Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Brick

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	<u>✓</u>	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 story plantation plain house with outside brick chimney. Front porch with turned posts & railing. 6/6 light windows. Tin roof. Gable with boxed ends & returns. c 100 yrs. old according to Mrs. Nix.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date \_\_\_\_\_



R16,36

Number

Lumpkin  
County

Name of structure Stowers home

Location Lumpkin Co Park Road, II - near Avarna off Hwy 9E

Present owner Stowers

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Victorian Cottage

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	_____	_____	_____
Grounds	<input checked="" type="checkbox"/>	_____	_____	_____
Neighborhood	<input checked="" type="checkbox"/>	_____	_____	_____

Notes:

1 story frame with 2 external stone chimneys. Front gable with  
files. East lake style porch extending across front & side. 6/6 light windows  
flat-cut work slate

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 January

Gene Thurston

R 16, 10

Number 50

County Lumpkin

Name of structure Auraria - The Church of the Almighty God

Location Hwy. 9E in Auraria

Present owner Church of the Almighty God

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: White frame church with front gable and cornice board. 6/6 light windows. Transoms light above door. Small round louver in front gable.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

Name of structure Old Graham Hotel, Auraria

Location Hwy. 9E, Auraria

Present owner Clarence Woody

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	<u>✓</u>	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: Two story frame hotel with outside brick chimney, 4/4 light windows. Turned posts on both front + rear porches. Tin roof extends over porch.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: Significant as one of few remaining structures in old gold mining community of Auraria

Recommendations for National Register (single structure, district, priority):

State

Additional Comments:

c. 1833. It was one of many hotels built in Auraria, but it is the only one still standing. It is a two story, frame structure but now only at its original length. Important structure in gold rush days.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

Surveyor Dennis Thurston

ARCHITECTURAL SURVEY FORM

R16, 12

Number 52

County Lumpkin

Name of structure General Store in Aurora - Woody's

Location Hwy. 9E, Aurora

Present owner Clarence Woody

Original owner Architect/builder

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 2 story frame store with front A-line gable. 6/6 light windows.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

State

Additional Comments:

Mrs. Woody indicated that a saloon used to occupy this site. Store itself well over 100 years old. Part of old Aurora community.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January  
James Thurston

ARCHITECTURAL SURVEY FORM

R16,14

Number 53

County Lempkin

Name of structure \_\_\_\_\_

Location Highway 9E, Auraria

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 2 story frame with outside brick chimney. 4/4 light windows. 3 front dormers. Tin roof. Front and rear shed porches.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

c. 1890's; This house is located in Auraria, across from old Graham Hotel.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 Jan, 1976

R 16, 15

Number 54

County

Name of structure Woody residence

Location Hwy. 9E, Auraria - next to General Store

Present owner Deerene Woody

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Bungalow - III

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New front window

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 1 story box frame with 4 porch columns which meet A-line gable projecting over porch. 4/4 light windows. Brackets under eaves. Bungalow lower. Stone/brick outside chimney

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

ARCHITECTURAL SURVEY FORM

R 14, 16, 18

Number 55

County Lumpkin

Name of structure Antioch Baptist Church and Cemetery

Location  Hwy. 9E, Auraria

Present owner Antioch Baptist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Brick

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

Red brick church, established in 1833; reconstructed in 1968

line <sup>gables</sup> projecting over porch with Tuscan columns.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: Significant as old church in

Auraria community. Old hill cemetery has several civil war monuments  
surrounded by iron railing. Also important as burial place for old  
gold miners who lived around the Auraria community.

Recommendations for National Register (single structure, district, priority)

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

Don Stewart

Name of structure Anonymous - may be uninhabited

Location Aurelia - Hwy. 9E

Present owner \_\_\_\_\_

Original owner Architect/builder

DESCRIPTION

Style Plain style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan T-plan

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	<u>✓</u>	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

1 1/2 story frame with outside stone chimney. 4/4 light windows. Singular porch posts. Tin roof.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January, 1976

Surveyor Dann Thurston



Name of structure Anonymous - looks abandoned

Location Aurora - Hwy. 9E

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	<u>✓</u>	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

1 story board and batten with stone external chimney. 4/4 windows. Tin roof.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January 1976

Surveyor Dennis Thurston

ARCHITECTURAL SURVEY FORM

R1713

Number 58

County Linn

Name of structure Parks residence

Location Highway 19

Present owner Mr. Parks

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plain style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan T plan

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: Board and batten framing with 4/4 light windows. Tin roof. Front and side shed porch. Two doors off side porch. Rectangular porch posts. Interior brick chimney.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Mr. Parks did not know how old the house is or who owned it originally. He guesses that it is approximately 50-60 years old.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan 1976

P 17, 2-4

59

Number \_\_\_\_\_  
County Lundia <sup>check back</sup>

Name of structure Davis homeplace

Location  Hwy. 19

Present owner Robert Davis

Original owner Daniel Davis - grandfather of Robt. Davis Architect/builder

DESCRIPTION

Style Plain style - Greek detailing

Facade Material Frame

Outbuildings Well house & smokehouse

Plan Central hall; T plan

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 1 1/2 story frame with two external ~~stone~~ brick chimneys. 4/4 light windows. Front shed porch with rectangular posts. Side shed porch has balustrade (single post) in roof. Cornice board under eaves. Side lights around front door. Carved detail above windows at front of house. Well house has shingled roof and brackets.

SIGNIFICANCE Modestly evocative of details over windows  
 Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):  
Single structure - state

Additional Comments:  
 This house was built by the present owner's grandfather, c. ~~120~~ 120 years old.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Surveyor Dennis Thurston

ARCHITECTURAL SURVEY FORM

P 17, 5-6

Number 60

County Lumpkin

Name of structure Anonymous - uninhabited

Location Hwy. 19

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plain style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan T plan

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	<input checked="" type="checkbox"/>	_____	_____
Grounds	<input checked="" type="checkbox"/>	_____	_____	_____
Neighborhood	<input checked="" type="checkbox"/>	_____	_____	_____

Notes:

1 1/2 story frame with T projection. Porch extends across front and long side - 3 doors across front and 2 along side. Rear shed porch, also. Central internal stone chimney. Tin roof. Cornice board under eaves and flat returns. 4/4 light windows

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Looks vacant

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan., 1976

Surveyor [Signature]

Name of structure Etowah Baptist Church

Location Hwy. 9E

Present owner Etowah Baptist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New roof - weatherboarding

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: Frame church established in 1897. A few Victorian monuments in cemetery.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):  
\_\_\_\_\_

Additional Comments:

ARCHITECTURAL SURVEY FORM

R16, 34 Number 62 Lumpkin County

Name of structure Soules Chapel Methodist Church

Location Old Gold Road - off Hwy. 9E in Auraria

Present owner Soules Chapel Methodist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New windows

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: White frame church with front gable with cornice board.  shingles  
Small front gable over front door

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 January, 1976

Surveyor John B. Thurston

Name of structure St. Paul's United Methodist Church

Location Hwy. 60

Present owner St. Paul's United Methodist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Late Victorian

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Addition on left side

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

White frame church with scalloped like cornice board at corners. Good gables; smaller gable enclosed over entry way.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

Ken Thurston

R 15, 24, 25

Number 64

County Lumpkin

Name of structure \_\_\_\_\_

Location Hwy. 60 - South

Present owner H. M. Poore

Original owner Steve Poore Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Log

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Weatherboarded section added c. 50 years ago; outbuildings added later.

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

log house which has been connected with log kitchen by weatherboarded stone exterior chimney. Saddle notched logs.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

According to obituary in DeKalb County Signal, 10/30/1891, Stephen Poore was 86 yrs old at time of death. He came to county in 1836. (Born in 1805)

Historical (Local, State, National) Discuss: Thought to be oldest structure in Lumpkin County

Recommendations for National Register (single structure, district, priority):

Single structure - still

Additional Comments:

According to Mrs. H. M. Poore, this log cabin was built in 1815 by H. M. Poore's great great grandfather. H. M. Poore's father added middle part which is weatherboarding, to connect original cabin with log kitchen. Mrs. Poore's husband has heard it told through the generations that the Cherokee Indians had a discussion of peace there.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January 1976

Jenny Thurston



Name of structure Old Welchel Place

Location  Hwy 60 (south)

Present owner C.C. Gilbert

Original owner Welchels Architect/builder \_\_\_\_\_

DESCRIPTION

Style Pl. Plain style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

2 story frame with 2 external brick chimneys. Front porch with turned posts and brackets, <sup>the</sup> scroll-work balustrade. 7/4 light windows. Shed porch at rear with fan roof.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

This was originally owned by one of the three Nicely sisters, all of whom lived in similar types of Plantation Plain houses within proximity of each other, near Hwy. 60. This particular Nicely sister married Mr. Welchel

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January

Surveyor Jean Thurston

Name of structure Old London Farm - now called Gold Creek Farm

Location Hwy. 60 (south)

Present owner Carl Hartrempf (Doctor in Atlanta)

Original owner M.M. London Architect/builder

DESCRIPTION

Style Pl. Plain-style

Facade Material Frame

Outbuildings Old London Store

Plan

Alterations

Condition	Good	Fair	Poor	Endangered
Structure	✓	_____	_____	_____
Grounds	✓	_____	_____	_____
Neighborhood	✓	_____	_____	_____

Notes:

Two story frame with 2 outside brick chimneys. Cornice board and returns in side gables. Front porch has turned posts, and second story with balustrade roof. 6/6 light windows. Transoms & sidelights around front door. Louver in center of roof. Original mantel inside is solid walnut. Hand planed ceiling.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Structure group - local

Additional Comments:

This house is currently being restored by Dr. Hartrempf. He thinks the house is over 100 years old. The house faces away from Hwy. 60 because when it originally built it was on the stage route from Gainesville to Dakinaga. The old London Store which was on the old stage road still stands. This house was originally owned by Mr. M.M. London who married one of the Nicely sisters. The two other Nicely sisters married a Mr. Welch and a Mr. Carby and lived in similar houses near by, which still stand.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January 1976

Surveyor Jerrin Thurston

Name of structure \_\_\_\_\_

Location County Road 52576 (off Hwy. 60 south)

Present owner Hoyt Robinson (mailbox)

Original owner W.M. Early Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings barn - <sup>a comb</sup> - log

Plan Central hall

Alterations Covered with white shingles

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: one story frame with 1st & 2nd story porches with square columns and single rail balustrade. Tin roof. 4/4 light windows. External stone chimney. Porch out building may be new.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

This house was originally owned by Mr. Early who married one of the Nicely sisters. All three sisters lived in similar houses within close proximity.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 9 January 1976

Surveyor John Thurston

ARCHITECTURAL SURVEY FORM

17, 28

68

Number

County

Hampton

Name of structure

Location Pony Lake Road

Present owner John Sosebee

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Log, corn crib

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

Small log crib with metal roof

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Surveyor

Jerry Thurston

Name of structure Anonymous

Location Whitchel Rd - across from Pony Lake Camp

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Log cabin crib

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	_____	_____	_____	_____

Notes: Log crib with tin roof

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Anonymous structure

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Surveyor Gene Thurston

p 17, 26

70

Lumpkin  
County

Number

Name of structure Peck home

Location Hwy. 115 (South)

Present owner C.O. Peck

Original owner C.O. Peck

Architect/builder \_\_\_\_\_

DESCRIPTION

Style Victorian cottage II

Facade Material Frame


Outbuildings (country) old general store

Plan Asymmetrical

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

1 1/2 story frame with hipped roof. Tuscan columns on porch; <sup>scalloped-shaped</sup> arches  
 over front and side. Front gable with tiles. Internal stone chimney. <sup>Detail</sup>  
 under porch cornice. Windows -  Metal roof

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

The house was built in c. 1925

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Surveyor John Thurston

ARCHITECTURAL SURVEY FORM

R17,25

71

Number

Sumner County

Name of structure 777 Olive Baptist Church

Location Off Hwy. 115 (south)

Present owner 777 Olive Baptist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Additions in rear

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Frame church with front gable and twin belltowers. 6/6 light  
dows and stained glass. Cornice board. Louvers in front gable and belltowers.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Established in 1921

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

John Thurston

ARCHITECTURAL SURVEY FORM

72

\_\_\_\_\_  
County Langston

Number

R17, 27

Name of structure Peck residence

Location Hwy 115 (South)

Present owner Owen Peck

Original owner Joe Sullens Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

1 story frame with two outside ~~stone~~ chimneys - one stone & one is stone, brick. 4/4 light windows. Tuscan type porch posts. Detail under porch eaves. Front gable projects toward street with scalloped-shaped tiles. Cornice board under eaves.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

c. 70 years old according to C.D. Peck

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Surveyor Owen Thurston



ARCHITECTURAL SURVEY FORM

R17,24

Number 73

County Lumpkin

Name of structure Hickory Grove CME Church

Location Hwy. 115 (south)

Present owner Hickory Grove CME Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Additions at front and rear

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	_____	_____	_____	_____

Notes: Frame church with gable and bell tower on left side. Additions on front & rear. 6/6 light windows. No date of establishment obvious

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Surveyor Jerry Thurston

ARCHITECTURAL SURVEY FORM

74

Humpton  
County

R17, 22, 23 Number

Name of structure Old Shepherd place

Location  Hwy 115 (south)

Present owner Gordon Mays

Original owner Shepherd Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plain style with variations

Facade Material Frame

Outbuildings Smokehouse + several sheds

Plan T-plan

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

1 story frame with two outside stone chimneys. 6/6 light windows.

porches - front, side and rear. Tin roof.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

According to Mr. Mays, part of house is c. 80 years old.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Surveyor Lynn Thurston

ARCHITECTURAL SURVEY FORM

RF, 20-21 Number 75 Levy County

Name of structure Burned - 1992-3?

Location  Hwy 115 (south)

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plantation plan with additions

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Right side of facade appears later and rear portion

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	_____	_____	_____	_____

Notes: 2 story frame with 3 bond doors. 6/6 light windows. Grooved weathering. Square porch posts. Stone external chimney. Perhaps right section of porch was added later. Tin roof. Rear shed porch

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan 1976

Surveyor Gene Thurston

ARCHITECTURAL SURVEY FORM

Number 76

County Lumpkin

Name of structure 81712  
Brown residence

Location  Hwy 115 (east)

Present owner Sam Brown (mailbox)

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Victorian Cottage (central gable)

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New door

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 1 1/2 story frame with diamond-shaped files in front gables. Sidelights around door (new). Type of turned porch posts; <sup>plaster</sup> brackets. 4/4 light windows. External brick chimney. Tin or metal roof.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan 1976

Surveyor Jerry Thurston

ARCHITECTURAL SURVEY FORM

R17,13

Number

77

County

Lumpkin

Name of structure

Location Hwy. 52 (east)

Present owner Barbara Walker & husband

Original owner O'Kelley

Architect/builder

DESCRIPTION

Style

Facade Material Frame

Outbuildings

Plan Assymetrical

Alterations

Condition	Good	Fair	Poor	Endangered
Structure	✓	_____	_____	_____
Grounds	✓	_____	_____	_____
Neighborhood	✓	_____	_____	_____

Notes:

1 1/2 story frame with hipped roof, ~~steep~~ steep front gable with diamond shaped tiles. Chaired porch posts; brackets. Internal brick chimney. Fluted beading around bay window in front. E-windows. Porch extends across front & along both sides. Cornice board under eaves

SIGNIFICANCE

Architectural (Local, State, National) Discuss:

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Gene Thurston

Name of structure Old Abercrombie place <sup>R17, 14</sup>

Location Highway 52 (east)

Present owner Dockerys

Original owner D. Abercrombie Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings Smoke house, well house

Plan Central hall

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 1 1/2 story frame with 4/4 lead windows, 2 outside brick chimneys  
gabled weatherboarding. Square porch posts. <sup>Diamond-shaped</sup> Tiles in front gable. Enclosed  
shed porch at rear.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan 1976

Surveyor Jerry Thurston

ARCHITECTURAL SURVEY FORM

R 17, 16, 17, 19 Number 79

County Linn

Name of structure Barnes residence

Location off Hwy 52 (east) in SE corner of county

Present owner Mrs. K.D. Barnes

Original owner Abercrombies Architect/builder \_\_\_\_\_

DESCRIPTION Style Version of Plantation Plan

Facade Material Frame

Outbuildings Barn, waterwheel

Plan \_\_\_\_\_

Alterations Right side appears to have been added later

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 2 story frame with outside stone/brick chimney. 6/6 light windows. Tin roof. 2 porches (1st & 2nd story) at front and rear with balustrade. 5 front doors. Perhaps right side added later.

SIGNIFICANCE Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

According to Mrs. Barnes the house is over 100 years old. Old mill wheel is across the road from the Barnes house on the property of the Abercrombies.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Surveyor Jerry Thurst

ARCHITECTURAL SURVEY FORM

Number 80 Hamilton  
County

R 7, 15

Name of structure \_\_\_\_\_

Location  Hwy 52 (east)

Present owner  Ed Carroll

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style  plain style

Facade Material  Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	_____	_____	_____	_____

Notes:  1 story frame with 4/4 light windows, tin roof; external brick chimney. Front and rear shed porches.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

According to Mr. Carroll's neighbor, Mrs. Dockery, the house is 80-90 years old. He was not home, but is 90 years old.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date  16 Jan, 1976

Surveyor  Dennis Thurston



ARCHITECTURAL SURVEY FORM

P17,9

Number 81

County Lumpkin

Name of structure \_\_\_\_\_

Location Highway 115 (east)

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Victorian Cottage (II)

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New windows in front

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	_____	_____	_____	_____

Notes: 1 1/2 story frame with fan-like tile in front gable. Central internal  
 brick chimney. Cornice board under eaves, hipped roof; enclosed shed porch in rear.  
 Front porch has chamfered posts, brackets and balustrade.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 January

Surveyor Sammy [unclear]

ARCHITECTURAL SURVEY FORM

R 17, 10411

82  
Number

Lumpkin  
County

Name of structure Mt. Zion Baptist Church + Cemetery

Location Highway 115 (east)

Present owner Mt. Zion Baptist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New windows

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: white frame church with 2 belltowers on either side of front gable.   
Painted board; A-shaped louvers, looks like new windows. Victorian   
monuments in cemetery. 4/4 windows, except in front. Hipped roof over belltowers.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Surveyor Sandra Thurston

ARCHITECTURAL SURVEY FORM

Number 83 County Lumpkin

Name of structure Beasley home

Location County road 796 - just east of Phillippi Church

Present owner Donelle Beasley

Original owner Charles Beasley Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plain style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Double Pen

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 1 story double pen frame with 6/6 light windows; Tin roof; chamfered  
 porch posts. Central interior brick chimney. Shed porch extends across front and  
 partially along side.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

According to Mrs. Beasley the house was built in the 1870's.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan 1976

\_\_\_\_\_

R17,30

Number 84

County Hampden

Name of structure \_\_\_\_\_

Location Rock House Road off Hwy 52 (east)

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Tin

Outbuildings partial log barn

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	<u>✓</u>	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

2 story frame with 6/6 light windows. Tin roof. Cobble over porch. 2 square posts and small balustrade. T projection in rear. Partial log barn. Side shed porch. Internal stone chimney.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Notice says "Shopping Center Site" - uninhabited. This house is located on a lovely site.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 16 Jan, 1976

Ann Thurston

ARCHITECTURAL SURVEY FORM

85  
Number

Lumpkin  
County

R18,33

Name of structure Anonymous

Location Road east off Concord Church - off Hwy. 19/north

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Log

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	<u>✓</u>	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

log house with ripped roof. Remnants of central stone chimney.  
Saddle notched. Ten roof. 4/4 light windows

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure; district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 Jan, 1976

Van Houston

ARCHITECTURAL SURVEY FORM

R 18, 24

Number 86

Levy County

Name of structure Anonymous Log shed

Location Winter Springs Road

Present owner

Original owner Architect/builder

DESCRIPTION

Style

Facade Material Log

Outbuildings

Plan

Alterations

Condition	Good	Fair	Poor	Endangered
Structure	---	✓	---	---
Grounds	✓	---	---	---
Neighborhood	✓	---	---	---

Notes: log shed with tin roof

SIGNIFICANCE

Architectural (Local, State, National) Discuss:

Historical (Local, State, National) Discuss:

Recommendations for National Register (single structure, district, priority):

Additional Comments:

This site depicts a trace of older settlement in this county, but many of the houses have burned and are no longer standing. Present farms may have incorporated older outbuildings. Or, perhaps, log was a building material used later in this county.

Photos: Roll# Negative #

Date 20 January 1976

ARCHITECTURAL SURVEY FORM

R 18, 28

Number 87

County Leungkin

Name of structure Seabolt home

Location off Porter Springs Road

Present owner Monroe Seabolt

Original owner Seabolts Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings Small log barn

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	<u>✓</u>	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

Board and Batten, one story with 2 external stone chimneys. 4 light windows. Tin roof.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

According to a neighbor, the house is c. 1880's.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January 1976

Oliver Thurston

ARCHITECTURAL SURVEY FORM

R 18,26,27 88 Number Lumpkin County

Name of structure \_\_\_\_\_

Location Porter Springs Road

Present owner Garnet Dyer

Original owner John Tate Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New windows on first floor

Condition	Good	Fair	Poor	Endangered
Structure	_____	<input checked="" type="checkbox"/>	_____	_____
Grounds	<input checked="" type="checkbox"/>	_____	_____	_____
Neighborhood	<input checked="" type="checkbox"/>	_____	_____	_____

Notes: 2 story frame with 3 outside stone chimneys. Two porches - <sup>front</sup> each story; square porch posts downstairs. Side porches (both stories).  
 Cornice board. 4/4 light windows. Roof of house extends over both front + rear porches.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Built c. 1880's according to Mr. Dyer

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January 1976



ARCHITECTURAL SURVEY FORM

R16, 20, 24, 25 Number 89

Hampton County

Name of structure Old Colonel Farrell home

Location Hwy 19 (north)

Present owner Lewis Whitnass (live in Atlanta)

Original owner Colonel Farrell Architect/builder

DESCRIPTION

Style


Facade Material Log

Outbuildings log well house

Plan

Alterations Porch now screened

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: 1 1/2 story log house with tin roof and 2 internal stone chimneys. Front porch with balustrade. Double side gables. Windows 

SIGNIFICANCE

Architectural (Local, State, National) Discuss:

Historical (Local, State, National) Discuss:

Recommendations for National Register (single structure, district, priority):

Additional Comments:

This house was built by Col. Farrell who built the Porter Springs Hotel. upkeep and newer frame part of house from Porter Springs Hotel. C 75-80  
as old

Photos: Roll# Negative #

Date 12 January

Jenny Thurston

ARCHITECTURAL SURVEY FORM

R16,26

Number 90

County Lebanon

Name of structure Martin cabin

(1) Location Hwy. 19 (north)

Present owner W. H. Martin

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Log

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	<u>✓</u>	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

1 story log cabin with stone exterior chimney. 4/4 light  
 (1) logs. Tin roof. Used for storage. Front shed porch. Has been  
 moved from original site c. 2 miles away. c. 100 yrs. old.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 12 Jan.  
W. H. Martin

ARCHITECTURAL SURVEY FORM

91

Lumpkin  
County

R18,29

Number

Name of structure Tate residence

Location <sup>Road east</sup> Off Hwy. 19 (with)

Present owner Tates (mailbox)

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Blair style

Facade Material Frame

Outbuildings Barn, shed - partially log

Plan T-plan

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	_____	_____	_____	_____

Notes: 1 1/2 story frame with 3 external stone chimneys, Front and side porches with lattice balustrade and chamfered posts. 4/4 light windows. Tin roof.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Structure group - local

Additional Comments: House occupied by Ada Tate and sister. Ada said residence willed to her + sister by father + mother. Has lived there all her life. One out building use to be old store, now serves as rental. Jaeger 1979. Nov.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January 1976

Surveyor De. J. J. J. J.

ARCHITECTURAL SURVEY FORM

R 18, 30, 31

Number 92

County Lumpkin

Name of structure \_\_\_\_\_

Location Road south of Turners Corner - off Hwy 19 (north)

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings Barn, corn crib - partially log

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

Frame house with 2 external stone chimneys 6/6 light windows  
 of house projects over porch.  
 Transverse crib (as termed by Olesie) with logs to shoulder with frame  
 over and lattice above. Tin roof

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 Jan, 1976

ARCHITECTURAL SURVEY FORM

R16, 24-29 Number 93

Lumpkin  
County

Name of structure Brady place

Location  Hwy. 19 (north)

Present owner Carson Brady

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings Barn

Plan \_\_\_\_\_

Alterations Newer front porch

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 2 story frame with external stone chimney. Front shed porch with posts on iron brick bases. Tin roof, sidelights around door. Rear shed porch. Cornice board under eaves. Barn has multiple gables with tin roof - very different design

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 12 January  
Jerry Thurston

ARCHITECTURAL SURVEY FORM

R16, 31, 32 94

Lumpkin County

Number

Name of structure Old Mt. Pisgah Church & present church + cemetery

Location Highway 19 (north)

Present owner \_\_\_\_\_

Original owner Architect/builder

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

Present church not too old. Old church is frame with 4/6 light windows. roof. Front & rear A-line gables. Front porch

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 12 Jan

Thomas Thurston

ARCHITECTURAL SURVEY FORM

R14,30

LU-00-95  
Number

Sumpter  
County

Name of structure Old Turner stone

Location Highway 19, near junction of 129

Present owner Mrs. T.W. Turner

Original owner T.W. Turner Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: Frame stone built in 1928. Stone originally occupied downstairs; residence upstairs. 2 story with 6/6 light windows. Tin roof covered weather boarding.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 12 January  
1960 Thurston

ARCHITECTURAL SURVEY FORM

R 18,34

Number 96

County Lemington

Name of structure \_\_\_\_\_

Location Just west of Yahoole Church - off Hwy 19 (north)

Present owner Loyd Gooch (mailbox)

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings Log barn

Plan \_\_\_\_\_

Alterations Rear shed porch enclosed.

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

1 story frame with 2 outside stone chimneys. Rear shed porch (enclosed)

road.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Looks uninhabited. There is another old house on site but in deteriorated condition.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 Jan, 1976

\_\_\_\_\_



ARCHITECTURAL SURVEY FORM

R 16, 21

Number 97

County Lumpkin

Name of structure Concord Baptist Church

Location  Hwy 19 (north)

Present owner Concord Baptist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Brick

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: Established in 1897; reconstructed, 1972. Brick with 6/6 light windows with fanlights.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

\_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 12 Jan

Surveyor James Thurston

218, 19

98  
Number

Sumpter  
County

Name of structure Bethlehem Baptist Church

(C) Location Black Farms (USIA Training Area) road - off Hwy. 19 (north)

Present owner Bethlehem Baptist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations Now covered with white shingles

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: White frame church with 9/6 light windows. 1 porch post  
on brick base (other one has been removed)

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

This church is no longer in use - a new one has been built  
next to it. Established 1839.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January, 1976

Surveyor John Thurston

ARCHITECTURAL SURVEY FORM

Number 99

County Lumpkin

Name of structure R18, 17, 18  
Howards residence

Location Black Farms (USA Training Area) Road - off Hwy. 19 (north)

Present owner Howards (mailbox)

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New windows on east side

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	_____	_____	_____	_____

Notes: 1 story frame with 9/6 light windows in front part of house  
4/6 in rear. roof of house extends over porch. Channeled porch posts.  
2 external brick chimneys. Tin roof. Cornice board and returns.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January 1976

Surveyor Thomas Thurston

ARCHITECTURAL SURVEY FORM

218,16

100  
Number

Lempkin  
County

Name of structure Log barn

Location Black Farms (USA Treasury Area) road - off Hwy. 19 north

Present owner Floyd Beck

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Log

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes: Log and frame barn with tin roof.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January 1976  
No photos taken

ARCHITECTURAL SURVEY FORM

R18, B

NO LONGER  
EXIST 101  
Number

Lumpkin  
County

Name of structure Anonymous - vacant

Location Black Farms (USA Training Area) Road off #17 (north)

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plantation Plain

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Central hall

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	✓ _____	_____
Grounds	✓ _____	_____	_____	_____
Neighborhood	✓ _____	_____	_____	_____

Notes:

Plantation plain style with 2 external stone chimneys. 9/6 light windows.  
Irregular porch posts on shed porch. Tin roof. Rear shed porch.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Vacant

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January 1976

No structure

ARCHITECTURAL SURVEY FORM

RR, 14, 15

102  
Number

Lumpkin  
County

Name of structure Log house - anonymous + vacant

Location Black Farms (USA Training Area) Rd - off Hwy. 19 (north)

Present owner \_\_\_\_\_

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Log

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	<u>✓</u>	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: Log house with metal roof + external stone chimney.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments: Vacant

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January 1976  
Da. Thruout

ARCHITECTURAL SURVEY FORM

Number 103

County Lumpkin

Name of structure <sup>R18, 12</sup> Log house

Location Oak Grove Church Rd - off 19 (west)

Present owner Clayton Rider (mailbox)

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Log

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes:

Log house with external stone chimney

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date \_\_\_\_\_

Name of structure Anderson residence

Location Off Hwy. 52 (west) - on Nimblewell Creek

Present owner Leland Anderson (mailbox)

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plain style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Double pen with T-projection

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 1 story frame with an external stone chimney Double pen with 4/4 light windows. Rectangular porch posts. Tin roof. Rear shed porch. Nice site on Nimblewell Creek.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No one home

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 January 1976

De... Thurston



Name of structure Cronan residence

Location Hamblewell Church Rd.

Present owner J.C. Cronan (mail box)

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plain style

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan Saddle Bag

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: 1 1/2 story frame with tin roof and central <sup>internal</sup> stone chimney. Front porch with rectangular posts on brick bases. Cornice board under eaves. 4 light windows

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

\_\_\_\_\_

Recommendations for National Register (single structure, district, priority):

Additional Comments:

ARCHITECTURAL SURVEY FORM

218,4

Number 106

County Lumpkin

Name of structure Nimblewell Baptist Church

Location Nimblewell Church Rd off 52 (west)

Present owner Nimblewell Baptist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<u>✓</u>	_____	_____	_____
Grounds	<u>✓</u>	_____	_____	_____
Neighborhood	<u>✓</u>	_____	_____	_____

Notes: White frame church with fan-like weather boarding around eaves in front gable. 6/6 light windows. Cornice board under eaves.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_  
\_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_  
\_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 Jan, 1976

James Thurston

R18,6,7

Number 107

County Lumpkin

Name of structure Sov's residence

Location Nimblewell Church Road off Hwy. 50 (west)

Present owner Bobbie Loves (mail box)

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style Plain style

Facade Material Frame

Outbuildings Log shed

Plan Saddle bag

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	_____	_____	_____	_____

Notes: 2 story frame with outside brick chimney on T-projection at central internal chimney. 4/4 light windows. 2 doors and 2 windows in front. Front shed porch. Tin roof. Cornice board under eaves. Log shed in foreground. Porch has pierced posts & turned balustrade.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 Jan, 1976

Surveyor Gene Thurston

ARCHITECTURAL SURVEY FORM

RIP, 8, 9

Number 108

County Lumpkin

Name of structure Fowler home

Location Wesley Chapel Rd. off 52 (west)

Present owner Lloyd Fowler

Original owner Fowlers

Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings Barn, shed

Plan Asymmetrical

Alterations \_\_\_\_\_

Condition	Good	Fair	Poor	Endangered
Structure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Neighborhood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Notes:

2 story frame with both 1<sup>st</sup> and 2<sup>nd</sup> story porches extending around 3 sides of house. Taped porch columns and Eastlake balustrade. 4/4 light windows <sup>carved</sup> in doors. One external brick chimney and one external stone/brick chimney. Detail

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

Mrs. Fowler was not sure of the age of the house but  
 " it was built c. 1900.

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 Jan, 1976

ARCHITECTURAL SURVEY FORM

R 18, 10, 11

109  
Number

Lumpkin  
County

Name of structure Wesley Chapel United Methodist Church and Cemetery

Location Wesley Chapel Rd - off 52 (west)

Present owner Wesley Chapel United Methodist Church

Original owner \_\_\_\_\_ Architect/builder \_\_\_\_\_

DESCRIPTION

Style \_\_\_\_\_

Facade Material Frame

Outbuildings \_\_\_\_\_

Plan \_\_\_\_\_

Alterations New shingle roof

Condition	Good	Fair	Poor	Endangered
Structure	_____	_____	_____	_____
Grounds	_____	_____	_____	_____
Neighborhood	_____	_____	_____	_____

Notes: white frame church with belfry rising through front gable. Louvers  
 and top of belfry; belfry has a conical tin roof. 9/6 light windows. New  
 shingle roof. Ornate board with scalloped shape around edges. Cemetery has a  
 few Victorian monuments.

SIGNIFICANCE

Architectural (Local, State, National) Discuss: \_\_\_\_\_

Historical (Local, State, National) Discuss: \_\_\_\_\_

Recommendations for National Register (single structure, district, priority): \_\_\_\_\_

Additional Comments:

No date of establishment obvious

Photos: Roll# \_\_\_\_\_ Negative # \_\_\_\_\_

Date 20 Jan, 1976

*Ann Shurston*